

Manhole Inspection Summary

Manhole # S09YY1008MH

Printed On: 12/17/2008

Page 1 of 3

Inspection Is Incomplete Rating: **2) Good**

Record Plat: **09YY1** Node: **008** Status: **Found**

Insp Date: **8/1/06 11:30 AM**

Incomplete Comments

Crew: **JJ, TD**
Inspector: **Jensen, J**
Firm: **RKK**

Location Address: **2707 WHITNEY AVE**

Cross Street: **BERKELEY AVE**

Manhole Type: **Diversion** Location: **Grass**

Ground Conditions: **Dry**

Prev. Rehab Weather: **Dry**

Subject To Ponding: **None**

Comments

Cover Shape: **Circular** Diameter: **24** (in.) Length: (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **2** (in.) Condition: Sound Cracked Leaks

Chimney / Frame Adjustment Exists Material: **Brick** Parged Height: **4** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None **Joint** Cracks Mortar Roots Wall

Corbel Material: **Brick** Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None **Joint** Cracks **Mortar** Roots Wall

Barrel Material: **Brick** Parged

Shape: **Circular** Diameter: **48** (in.) Length: (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Bench Exists Material: **Brick** Parged Debris (not Condition related)

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Brick** Parged Debris (not Condition related)

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: Sound Cracked Root Intrusion Deteriorated Leaks **Debris**

Steps Count: **3** Missing: **0** **Corroded**

Surcharge Evidence Of Surcharge Depth: (ft.) Active Surcharge Present


Location View



Top View



frame offset



corbel



Defect



debris in channel

**8 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock**



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **7.64** (ft.) Flow Characteristics: **None**

Deposits: None Mud Sludge Debris Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **Evidence** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

**8 in. Circular Gravity Sewer
Pipe In @ 9 O'Clock**



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **7.59** (ft.) Flow Characteristics: **None**

Deposits: None Mud Sludge Debris Grease

Silt Depth: (in.) Deposits Extent:

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection